



Project: **MECA INOX**

Client: **S.N.E.R**

Office: **LYON**

Client's Order Number: **Signed Fee Request**

Date: **25 September 2016**

Order Status: **Complete**

Inspection Dates

First: **8 October 2009**

Final: **08 octobre 2009**

This certificate is issued to

S.N.E.R GAILLON FRANCE., to certify that at their request , H.WALLE, a Surveyor to LLOYD'S REGISTER EMEA did attend their works at ,Z.I. La BERGERIE 27 GAILLON (FRANCE) on the 8 October 2009 in order to witness fire test carried out on:

ONE ROBINET A BOISSEAU PHERIQUE DN 50 PN 40 . CODE ARTICLE R2H4L9NI- Dwg :15066
Makers stated: MECA-INOX FRANCE


The test has been performed according to EN ISO 10497 , and S.N.E.R. procedure N° PP 0287/9243-01/A requirements.

The valve pressurised to 2 b was then submitted to a fire test during 30 min; during the test the average temperature of the calorimeters was found above 650 °C. During the test the internal pressure of the valve, the flame temperatures, the calorimeter temperatures have been recorded and are shown on the S.N.E.R. report N°S 36880 which is part of this certificate.

After the test, the temperature of the valve was decreased below 100 °C within 10 mn . The valve was submitted to new tightness test pressure at 2 b.during 5 mnn; and then repressurised at 30 b.to be operated.and the external leakage was checked
The valve body was found tight and passed the test .

All the test and checks gave satisfactory results, in accordance with EN ISO 10497 criteria. The SNER report has been endorsed accordingly.

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.



Certificate no:
Page 2 of 2

LYO 0900408/1 A

H. VALLE
Surveyor to Lloyd's Register EMEA

A subsidiary of Lloyd's Register Group Limited